

"A L I C E"

IT IS SUBMITTED the PLYMOUTH
Surveyor be advised that the flush scuttles
fitted do not appear to be in accordance with
D.2327/8 of the Rules and that they should be
requested to state where and when flush
scuttles in accordance with Rule requirements
will be fitted.

DA.

11.10.61.



© 2021

Lloyd's Register
Foundation

010874-010891-0140