

1

11

CANOPO

11

Sent to Chief Surveyors _____


Received from Chief Surveyors _____

VESSEL'S NAME *SEA S M/V* " *NORFOLD* " Report *Slc* No. *51000***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 34/5/92.)

Nature of Survey *1st Entry* When due *Revised Rules*

✠ 100 A.I. (Steel). Carrying Petroleum in Bulk.
 2 D^{cs} (Stl) + web frames, Longitudinal Framing
 Cell D.B. U E 81' 305t, D.T.f 38 498t, F.P.T. 113t, A.P.T. 129t
 F.K. 15 B.H. (5 B.H. to 2nd D^c) Plyds A CP.
 P 105', B 28', F 38'.
 Machinery aft.



© 2021

Lloyd's Register
 Foundation

010890-010908-0091

19.11.30