

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME "C. 871" REPORT HULL No. 66257.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine NON - PROPELLED

~~XXXXXXXXXXXXXXXXXXXX fitted with forced draught~~

~~XXXXXXXXXXXXXXXXXXXX fitted with a continuous liner~~

~~XXXXXXXXXXXX fitted with an outside gland of approved type~~

The Auxiliary machinery with pumping arrangements and secondary electrical installation fitted in accordance with approved plans, Secretary's letters and tested on completion.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

9.60 (DUMB BARGE.
OIL TANKER.

YJB

29.11.60.



© 2020

Lloyd's Register Foundation

010943 - 010952 - 0072