Ship's Name ~~SS/MS~~ "ZURRIOLA"

Gross tons 2078 Port of Registry San Sebastian Port Barcelona

Date of build 6-1899 Is there a rpt. 8? Yes Rpt. No. 7982

No. of visits 1 First date and Last date 11-4-64

Interim Cert. issued & copy herewith? No Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. 20-5-64 Surveyed at, if different from Port above

Is a rpt. 9A attached? No MN (185) Nature of survey D.D.

Survey fees Damage fee Expenses

NIL.

S.A. fee

DOCKING

Propeller Good

Sea connections Good

Oil gland -

Fastenings Good

Wear down of stern bush
(if relined, state clearance
before and after) 3.5 mm.Has screw/tube
shaft been drawn?

Date of examn.

Has shaft been
changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS

(State if oil fired—OF
or exhaust gas—EG)

MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors
and fasteningsSafety valves { Sat
adjusted to { SptBoiler securing
arrangements

Main economisers

Steam heated
steam generatorsForced
circulating pumpsHave saturated steam pipes in cylindrical boiler
smoke boxes been examined as required by the Rules?Exhaust gas heated economisers
and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system &
remote controls examined
in accordance with rules?I recommend that the machinery of this ship remain as classed ~~with~~/without fresh record of
Survey(Where conditions of class are recommended to
be retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)

Date of Committee

FRIDAY - 3 JUL 1964

J. Alday

Minute

ALSO FOR

SPL FOR


TRO

SRL

POSTING

HEADER

CERT



011047-011056-0216

or complete Special Surveys those items which are not applicable
the ship are to be cancelled; this need not be done when the machinery is
in a continuous survey basis. When any part has been subjected to pressure
test this should be stated. Engine parts when referred to by numbers should
be counted from forward.considered that re-examination or repairs should
be made before that date a distinguishing mark
must be inserted against the item and the
circumstances and action taken or recommended
described fully under "defects and repairs".The condition of any item is to be described as "good"
only when it has been examined, found or placed in
good condition, and is considered to be acceptable
until the due date of the next Periodical Examina-
tion. Where repairs have been effected or it is