

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME Sin.Sc.Motor Trawler ~~X~~ "NORDELITE" ~~X~~ REPORT Hul. No. 59337

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 105' B. 23.5' D. 11.5'


The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*100A1 "Motor Trawler"

"pt Elec. welded"
Wing tanks in mchy space O.F; DTf F.W.
BK 7", 4BH, Cem, Lloyd's A & CP
F 18'
O.L. 118.3'
ESD
Radar
"1"

REVISED CERTIFICATE


28.7.53.


© 2021

Lloyd's Register
Foundation

011057-011061-0325