

TONNAGE under  
Tonnage Deck...  
Do. between Tonnage Dk.  
and 3rd and 4th Dk.  
Total

1500, 1617.

Surveyors 24.4.18

Received from Chief Surveyors

NAME Shuess R. F. D. Petrella

Report Book

No. 17285

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

uses which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

When due

✱ 100A-1 (Steel) Carrying petroleum in bulk

10K (Steel) Well Deck


D.T. a 15E. F.P.T. 37E. a.P.T. 8E.

FK. 11BH pt Cen. Ledges and 263' BIS F 24

Michy aft

*M*  
24. 4. 18

© 2021



Lloyd's Register  
Foundation

011062-01070-0343

BEAWS, Upper D  
Angle  
In way of  
Spacing