

Are the cylinders fitted with safety valves yes

Are the exhaust pipes and silencers water cooled or lagged with non-conducti

Decr. 1908.

Humboldt - Security Motors A-G.

Engineer Nos. 473606-7-8-10.

It is submitted that report be
attached to the first entry report on
the M.V. "Marali", and the photographs
be retained in this office as referring
to the last two engines Nos. 473608-10.



© 2020

4/17/38.

Lloyd's Register
Foundation

011079-011038-0153

If the generators are 100 kw. or over have they been built and tested under survey