

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Pontoon* FLOATING CRANE N° *1* Rpt. *Indb* No. *14474*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

Transverse No. Depth "d"

Framing: Table No. Description *Longitudinal framing*

Longitudinal No.

Proportions $\frac{\text{Length}}{\text{Depth}} = 13.3$

~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ A - (Steel). "Crane Pontoon" for Harbour Service
1 D° (Stl) = Web Frames, Longitudinal framing.
TRIMMING TANK III E.
F.K, L.B.H, asp.

Indb 8/9/31

It is included the riveting and bracket attachments of the Longitudinal to bulkheads are as approved ~~but~~ ^{per} the surveyors should be requested to state if this is so



W.M.A.
8/9/31

Lloyd's Register Foundation