

COPY

# LLOYD'S REGISTER OF SHIPPING



Port SINGAPORE.

Date 19th December, 1959.

This is to Certify that I have surveyed the s.s. "LUEN HWA" 554 tons gross of PANAMA whilst afloat and in drydock at Singapore on the 26th November, 1959 subsequently on account of Docking and General Examination Damage stated to have been sustained due to contact with s.s. "KIM HWA" whilst afloat at Singapore on the 6th December, 1959, and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will recommend that she be continued as classed with fresh record Docking 11,19 subject to shell plate D2 (ssf) and aft deck plating and aft accommodation tween deck plating (eroded) being specially examined and dealt with by the Special survey.


*W. W. Taylor & MacLeod*  
 Surveyor to Lloyd's Register.  
 (W. W. TAYLOR).

#### KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
 "The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021



Lloyd's Register  
 Foundation