


REPORT ON SURVEY OF OIL TANK BARGE

Ship's Name :-	Adama Barge No.4
On Slipway from:-	20.5.63.
On Slipway to :-	25.5.63.
Shell Plating :-	In good condition generally.
Plating in way of shell openings :-	None.
Side scuttles and deadlights:	None.
Overboard discharges and scuppers :-	None.
Hold :-	None.
F.P. Spaces :-	Satisfactory.
A.P. Spaces :-	Satisfactory.
Weatherdecks :-	In good general condition. Two bollards rewelded on new doublers.
Deckhouses :-	None.
Skylights :-	None
Hatchways :-	Tank trunkings, Lids, packings and securing screws in good order.
Ventilators :-	None.
Air & Sounding Pipes :-	In good order, two new plugs fitted.
Doublers under sounding pipes :-	Not examined.
Masts and Rigging :-	Satisfactory.
Hand pumps and Suctions :-	In good order.
Bulwarks, freeing ports, etc.:	All lowerable stanchions and wire in good order.
Anchors, No. on Board :-	None fitted.
Mooring Ropes :-	Not examined.
Cargo tank spaces :-	Satisfactory.

The above is a true report on the condition of the above named craft and all repairs as stated were carried out in a satisfactory manner and tested where necessary.

Burutu 1.8.63.  
JWL/MDA.

AG. SUPT. ENGINEER - W.A.



© 2020

Lloyd's Register  
Foundation

011280-011293-0335