

FOR OFFICE REFERENCE ONLY

SPACE	EXAM <sup>P</sup>	TEST	REMARKS
F. P. T.	6.59 <input checked="" type="checkbox"/> 4.60	6.59	X REPAIRS IN THESE SPACES DEFERRED UNTIL SHIP REQUIRES TRD RECOMMENDED REPAIRS — BUT NOT EFFECTED
FOR <sup>P</sup> PUMP RM.	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
N <sup>O</sup> 1 CARGO TK (P)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " (S)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " £	6.59	6.59	
N <sup>O</sup> 2 " (P)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " (S)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " £	6.59	6.59	
N <sup>O</sup> 3 " (P)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " (S)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " £	6.59	6.59	
N <sup>O</sup> 4 " (P)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " (S)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " £	6.59	6.59	
N <sup>O</sup> 5 " (P)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " (S)	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
" " £	6.59	6.59	
c/dan of 43-41	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
OF BUNKER (P)			
" " (S)			
FEED WATER TK £			
A.P.T.	6.59 <input checked="" type="checkbox"/> 4.60	6.59	
	Cco Trd.	Cco Trd.	

TS INVERRUBA

S.S. (D) due 8.59

S.S. (D) commenced

Cco 6.59

See also CSSR

memo - re drillings

Remaining spaces

examined at Trinidad

but no repairs

effected

X REPAIRS DEFERRED

AT CCO TILL TRD

REPAIRS DEFERRED

TRD TILL LATER



© 2021

Lloyd's Register  
Foundation



# OIL TANKERS.

Cco.

Trd.

DOCKING	-	-	-	6,59 ✓	SHELL PLS	4,60 ✓	SHELL REPAIRS OUTSTANDING
HOLDS	-	-	-	-		-	
CEILING	-	-	-	-		-	
PEAKS SPACES	EXAM'D	FORO	6,59 ✓	4,60 ✓	FCLF DK		
BUNKERS	TESTED	AFT	6,59	4,60 ✓			
E. and B. SPACES (ABOVE & BELOW)	EXAM'D		6,59	4,60 ✓			
DEEP TANK	TESTED						
D. B. TANKS	EXAM'D						
MAIN TANKS	TESTED						
Do.	EXAM'D						
SUMMER TANKS	TESTED						
Do.	EXAM'D						
COFFERDAMS	TESTED						
Do.	EXAM'D						
PUMP ROOM			6,59 ✓	4,60 ✓			
DRILLING			6,59 ✓				
SIDELIGHTS			6,59 ✓	4,60 ✓			
DECKS			6,59 ✓	4,60 ✓	TRUNK, UPPER		
HATCHES			6,59	4,60	BOAT DK & CASINGS		
ANCHORS			6,59	4,60			
CABLES							
CHAIN L'KR			6,59 ✓	4,60 ✓			
MASTS							
RIGGING							
WEDGES							
STEERING GEAR				4,60 (S/G Capt 4,60 ✓)			
WINDLASS							
GENERAL EQUIPT.							
PUMPS			6,59				
W.T. DOORS			6,59				
VENTILATORS			6,59 ✓	4,60			
AIR and SDG. PIPES			6,59	4,60			
CARGO TANK STRUMS			6,59				
FREEBOARD			6,59	4,60			
TWO OK SPACES				4,60 ✓			

REPAIRS IN THESE SPACES DEFERRED OWNERS REQUEST TILL SHIP RETURNS TRINIDAD

RECOMMENDED REPAIRS BUT NOT EFFECTED



© 2021

Lloyd's Register Foundation



Position of S.S (D) as now.ITEMS & SPACES ACCEPTEDExamined Int & Tested :- CARGO TANKS N<sup>o</sup> 1 to 5 CentreExamined :- Oil Tight Hatches to Cargo Tanks N<sup>o</sup> 1 to 5 (P & S)  
Cargo Tank Strains (all).  
Pumps & W.T Doors.  
Engine & Boiler Spaces (above plates only).ITEM STILL OUTSTANDINGTo be examined & tested :- Oil Fuel Bunkers (P & S) at F.E Boiler Rm.  
Feed Water tanks (within aft peak) Aft end ER.  
Effortden in Bridge Space.To be examined :- Anchors & chain cables.  
Masts & Rigging  
Steering gear (main & auxillary)  
Windlass  
General Equipment.ITEMS EXAMINED / TESTED BUT REPAIRS OUTSTANDINGExamined int & tested :- Fore & Aft Peak Tanks  
~~Fore~~ Cargo Tanks N<sup>o</sup> 1 to 5 (P & S)  
Fore Pump Room  
Aft C/dampers 43-41Examined :- Drydocking (shell repairs not complete)  
Fore & Aft Peak Spaces  
Aft deck  
Chain locker  
E & B spaces (below plates)  
Drilling (as per C.S.R memo dated 17/11/59)  
Sidelights & plates in way



Examined - Decks - Upper, Trunk, Boat Dh  
(ent<sup>d</sup>) aft's deck & Tween decks & casings  
Steering Gear Comp't  
Ventilators  
Riv & Sanding pipes (striking plates included)  
Foreboard struts  
Hawse pipes

At present Notation of SS (Dr) 6,59 has been  
withheld pending completion of Special Survey  
and attending repairs

Trinidad report of 4/60 not yet endorsed. in view  
of the above



© 2021

Lloyd's Register  
Foundation