

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

*Marguerite Fivalg*

Rpt.

*Zri*

No.

*10248*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22).

Type of Engine

*oil engine 2 S.C. La.*

If Boilers fitted with forced draught

*no*

Tail Shaft. If fitted with a continuous liner

*yes*

If fitted with an outside gland of

*no*

approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*TAU 12:33.*

*20 B. (a) 200th*

*20 B. (f) 100th*

*It is concluded that adequate arrangements were adopted for the insulation & protection of the bare conductors for 2004 electric circuit & that this has been confirmed & full particulars furnished R.A. 30/12/33*

*20/12/33*



© 2021

Lloyd's Register Foundation

011368-01377-0187