

6 JAN 1964

Ship's Name ~~xx~~/MS "MASHONA COAST" Gross tons 413

Is there a rpt. 9? Yes Port CAPE TOWN Rpt. No. 6918

No. of visits 5 First date 9/12/63 Last date 18/12/63

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) CTN. 6801.

Date of completing rpt. 31/12/63 Surveyed at, if different from Port above

Surveyed afloat and ~~xx~~ in D.D. Both Last date of examination in D.D. 17/12/63

Has a Load Line Survey been held? N/A Freeboard Marks verified -

State which additional Rpt. 8 is attached: (~~Book~~); (PS); (~~DD~~); (~~EQ~~); (~~Box~~)

Survey fees R50.00 <sup>sup.</sup> Damage fee - Expenses R3.10

S.A. fee

18 JAN 1964

I have surveyed the above ship in accordance with the Rules for D.S., and General Examination for postponement of Special Survey for a further 4 months as per Circular 1959

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Now done for General examination: Vessel placed in dry dock and generally examined and found or placed in good condition: the following parts examined:- Keel, bottom, rudder shell and deck plating, casings, trunks, decks, machinery spaces, ventilators, hatchways, closing appliances, cofferdams (side and bottom), fore and after peaks and peak spaces, general equipment, steering gear, windlass, holds and deep tanks.

Now done for wear and tear repairs: Trunk above side cofferdams doubled at fwd end where locally thin.

S.R.L. No. 211: Stern plating, poop side plating (S.S.), stem plating specially examined and found to continue efficient.

The vessel as seen is in an efficient condition, it is submitted that the Special Survey be postponed for a further 4 months until March, 1964.

I recommend that this ship remain as classed with ~~xxxx~~ fresh record of dry docking 12/63 ; subject to all outstanding conditions attached to the vessel's class as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee WEDNESDAY 29 JAN 1964

Minute

*[Signature]*  
 Surveyor to Lloyds' Register of Shipping  
 D. ROSS INNES.

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

*[Handwritten notes]*  
 Defined for SS (by 12.63)  
 but further postponement SS until 3.64 approved  
 DS 12.63 subject (h.4m)  
 Link C. Thax pp SS.  
 011461-011468-0115 1/2

Lloyd's Register Foundation

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.  
 date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and  
 The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

RPT. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~xx~~/MS "MASHONA COAST"

S.S. ( G ) Due 12/62

Port CAPE TOWN

Rpt. No. 6918

	<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>
In dry dock from	17/12/63	* Air & sounding pipes	Good
" " " to	17/12/63	Doublers under part "	Good
Shell plating	Good	Steering arrangements (main)	Good
Sternframe	Good	" " (aux)	Good
Rudder	Good	Windlass	Good
Was rudder lifted?	No	Masts & rigging	Good
Plating, etc. in way of shell openings	-	Hand pumps and suction	-
Side scuttles & deadlights	Good	W.T. doors	-
Overbd. scuppers & discharges	Good	Bulwarks, freeing ports, etc.	-
F.P. spaces	Good	Summer freeboard as verified	-
Chain locker	Good		
A.P. spaces	Good		
Engine space	Good		
Boiler space	-		
		<u>EQUIPMENT</u>	
Under E. <del>scup</del>	Good	Equipment letter	G 20
Coal bunker	-	Fee ltr., if diff. from eqpt. ltr.	-
Tunnel & well	Good	Anchors: No. on board	3 B
Cement, asphalt, etc., on btm. shell	part Good	State if ranged	No
Weather decks	Good	Length on board	Stated complete
* Casings	Good	Mean dias. range from	to
* Deckhouses	Good	Rule length	Dia.
* Superstructures	Good	Mooring ropes	Good
* Skylights	Good		
* Companionways	Good		
* Hatchways	Good		
* Ventilators	Good		
Other items:			

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Lloyd's Register of Shipping  
 Surveyor to Lloyd's Register of Shipping  
 D. ROSS INNES.

0115 2/2