

Received London
19 SEP 1964

Ship's Name SS/MS "IWTA-FARIDPUR"

Gross tons 240

Is there a rpt. 9? YES

Port CHITTAGONG

Rpt. No. 638

No. of visits 1

First date and

Last date 1.9.64

Interim Cert. issued & copy herewith? YES

Damage rpt. issued & copy herewith? NO

Last rpt. (H.Q. only)

BMM 7189 (KE)

Date of completing rpt. 2.9.64

Surveyed at, if different from Port above

NARAYANGA NJ

Surveyed afloat and/or in D.D. AFLOAT

Last date of examination in D.D.

-

Has a Load Line Survey been held? NO

Freeboard Marks verified

-

State which additional Rpt. 8 is attached: ~~(Cert), (PS), (DR), (SQ), (Rig)~~

Survey fees

Damage fee

Expenses

G.E. = Rs. 75/=

Rs. 25/=

∞

S.A. fee

I have surveyed the above ship in accordance with the Rules for GENERAL EXAMINATION ON A RRIVAL
IN THE WORKING AREA:

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

The ship was examined afloat under working conditions and found to be in satisfactory condition.

I recommend that this ship ^{be} ~~remain as~~ classed ~~with~~ ~~without~~ ~~fresh~~ ~~record~~ ~~of~~ ~~dry~~ ~~docking~~ as contemplated.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee FRIDAY 30 OCT 1964

Minute See Bmm 7189

Ross

(A. ROSS)
Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR


TRO

SRL ✓

POSTING

HEADER

CERT



When any part has been subjected to pressure test this should be stated.
That re-examination or repairs should be made before that date the circumstances and

found or placed in good condition and is considered to be acceptable until the due