

15 FEB 1965

Ship's Name ~~SS/MX~~ "LEONIDAS" of Monrovia, Liberia Gross tons 13406
LR 520656
Is there a rpt. 8? No Port Balboa, C. Z. Rpt. No. 5308
No. of visits One First date and Last date 26 January, 1965
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) NNS. 8764
Date of completing rpt. 29-1-65 Surveyed at, if different from Port above LasMinas Bay, R.P.
Is a rpt. 9A attached? No MN Nature of survey Compl. MBS & Steam Generator survey
Survey fees Damage fee Expenses
\$60.00 \$15.00
S.A. fee

DOCKING
Propeller Sea connections Oil gland
Fastenings Wear down of stern bush
Has screw/tube shaft been drawn? Date of examn.
Has shaft been changed? Has shaft now fitted been previously used?
Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)
AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Port and Starboard

Air heaters
Superheaters
Safety valves
Mountings, doors and fastenings
Safety valves { Sat
adjusted to { Spt
Boiler securing arrangements
Main economisers Exhaust gas heated economisers
Steam heated steam generators Steam generator safety valves adjusted to
Forced circulating pumps Funnel
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of
MBS 9.64 as previously recommended. DF

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

MBS 1-64 Subject
SSS 27.64

NEW YORK

FEB 10 1965

Surveyor to Lloyd's Register of Shipping

S.O. Ltr.
N.Y.K.
22.2.65

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

011595-011602-0178