

F.E.
(FBD.)

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Screw M.S. "TROMA"

Rpt. Sld. No. 32174

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15089.7

Depth "d" 25.06

2nd Long. No. 37294

Proportions = $\frac{L}{D}$ 11.07

Framing Bulb angle frames as approved Sheerstrake As approved

This is a sister ship to the "RIPLEY"

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed ~~LOCAL~~ "With Freeboard"

'Carrying vegetable oil in deep tank'

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. & Shelter Dk.

Cell. DB 346' 1174t, MT^{41'} 1236t, APT 177t.

FK, 7 BH (Coll. BH to Shelter Dk. 6 BH to 2nd Dk.) pt. Cem., Lloyd's
O.L. 439' - 3" A & CP.



[Handwritten signature]
20.8.37

[Handwritten signature]



© 2021

Lloyd's Register
Foundation

DOUB
Solid