

COPY

Ship's name

"SAND SKIPPER"

Port

Sou.

28382 (a)

Sou.

28389 (b)

No.

Last survey date 1.3.63.

GB

Class is subject to

indented C.5 shell plate (p.s) and  
indented No.1 forecastle sheerstrake plate and deck plating  
in way (p.s) also to shell plates A.2, B.1, D.3 & 4 (s.s.a)  
being specially examined and dealt with as necessary next  
drydocking.

S.R.L. Appendix (as before or ~~none~~)x

Nature of present survey (afloat~~x~~ and~~x~~ in drydock)

- (a) Docking: Wear and tear repairs including renewal and  
verification of 15 fms. of c.c.
- (b) Docking on account of propeller damage.

Recommendation

SUBMITTED record of 'DS 8,63' be assigned,  
subject as above.


DS 8,63 Subject

IN S.R.L. APPENDIX.

Shell plates A.3 & 5, B.12 (p.s),  
A.11, B.11, C.6 (s.s) slightly indented.

End. S.1

011657-011664-0027



© 2021

C.S.S. Records Dept.  
to note.

Lloyd's Register  
Foundation