

Ship's name "WINAMAK"

Port

BMN

No.

7380

Last survey date 15.9.64.

Class is subject to

NONE

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Surveys due

SPECIAL SURVEY (C) due 9,65.

Nature of present survey (afloat and in drydock)

Docking: Commencement of S.S.

Contact damage and wear and tear repairs.

Is interim certificate in order

Yes/No/None

```

*-----Items outstanding if any for SS-----*

```

FOR PORTION OF SURVEY HELD:- See List in Ship Reports Dept.

SS proposed to be completed by

## Recommendation

SUBMITTED record of DS 9,64 be assigned, subject to wasted F.P. tank structure, tank top of (p & s) forward deep tanks, coaming of access hatch to aft cofferdam (p.s), structure in way of E.R. aft well and indented shell plates H.9 & 11, J.9 & 11 (p.s.from fwd) being specially examined and dealt with as necessary by the Special Survey.

DS 9,64 Subject

IN S.R.L. APPENDIX

Keel plate No.2 forward slightly set up.  
(Shell and deck plating to be drill tested 9,59).  
(Lengthened and amids portion renewed 9,57).

SHIP DEVELOPMENT TO NOTE

SLS. PART HELD.

As the defects reported do not require to be dealt with until the SS. It is submitted a

S.2 violation of Class withdrawn at Owner's request be assigned.

RSL  
13/11/64  
End

End.

(.69).

SLS.PART HELD.

6500-528110-528110