

- 7 JAN 1958 ^{4E}

Received by Chief Engineer Surveyor.....


Received from Chief Engineer Surveyor.....

SHIP'S NAME "VASCONIA"..... REPORT Lis. No. 7605.....

The starboard main engine bedplate cracked in three places in way of clutch and thrust bearings, repaired by welding and fitting mild steel straps. The Surveyor recommends that the starboard main engine clutch and thrust housing be specially examined at the next special survey.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED. *subject as now recommended.*

J.H. Cram
30.12.57.



© 2021

Lloyd's Register
Foundation

012089-012095-0261