

VERNICOS NICOLAOS
EX
Kumaki

F.E.

Received by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "ST. BOTOLPH" Rpt. Hul. No. 30999

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 45.14 Depth "d" 14.48

Framing: Table No. - Description Bulb angle as approved.

Longitudinal No. 6093.

Proportions Length = 8.36
Depth

Deck Sheerstrake and other scantlings as approved for the
A.1. class.



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed A.1. (Steel) "For towing purposes," as recommended.

- 1 Dk. (Steel).
- Cell DB u Bunkers 17' 19t. FPT 26t. APT 38t.
- BK.6. 3 BH. Cem. Lloyd's A. & C.P. F32'.



8. 4. 19.

no oil gland
no 29493
C.L. Albl
16/11/91



© 2021 Lloyd's Register Foundation

012108-012112-0131