

Lloyd's Register of Shipping.

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship S.T. "KUMAKI" Official Number 143063 Port of Registry London.
Place of Survey Abadan. Dates of Survey 3rd April, 1944. Date of last Load Line Survey 5th May, 1943.

PARTICULARS OF SURVEY.


Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS. INCLUDING SMALL HATCHWAYS.			
Exposed on freeboard deck.			
Platings, their stays and stiffeners...	Good.	None.	
Beams ...	None.		
Fore and afters ...	None.		
Covers ...	Good.(Steel)	None.	
Parpaulins ... (State number per hatchway)	None.		
Plats and battens ...	Bolts with winged nuts.	None.	
Washings and their fittings ...	Good.	None.	
Edges... (Is supply, including spares, adequate?)	None.		
Exposed on superstructure decks, including raised quarter decks.			
Platings, their stays and stiffeners ...	Good.	None.	
Beams ...	None.		
Fore and afters ..	None.		
Covers ...	Good.(Steel)	None.	
Parpaulins ... (State number per hatchway)	None.		
Plats and battens ...	Bolts with winged nuts.	None.	
Washings and their fittings ...	Good.	None.	
Edges ... (Is supply, including spares, adequate?)	None.		
Within superstructures not intact or not protected by Class I closing appliances.			
Platings ...	None.		
Beams ...	None.		
Fore and after ...	None.		
Covers ...	None.		
Parpaulins ... (State number per hatchway)	None.		
Plats and Battens ...	None.		
Edges ... (Is supply, including spares, adequate?)	None.		

19


LLOYD'S AGENCY

© 2021

Lloyd's Re





Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good.	None.	
Closing arrangements... ..	Good.	None.	
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good.	None.	
Closing arrangements... ..	Good.	None.	
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements... ..	Good.	None.	
7. Within partially enclosed superstructures.			
Closing arrangements... ..	Good.	None.	
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings	Good.	None.	
Skylights, their fastenings, covers and lashings	Good.	None.	
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good.	None.	
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	None.		
11. Within partially enclosed superstructures.			
Doors and fastenings	None.		
12. FLUSH BUNKER SCUTTLES and chain attachments.			
	None.		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good.	None.	



© 2021

Lloyd's Register
Foundation

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	GOOD ✓	NONE	
Bridge, fore end	NONE ✓	--	
Bridge, after end	NONE ✓	--	
Poop	NONE ✓	--	
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	NONE ✓	--	
16. SCUPPERS AND SANITARY DISCHARGE PIPES			
Valves	GOOD ✓	NONE	
17. SIDE SCUTTLES AND DEADLIGHTS			
	GOOD ✓	NONE	
18. GUARD RAILS			
	--	--	
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	GOOD ✓	NONE	
20. LIFELINES (fittings and material)			
	NONE ✓	--	
21. FREEING PORTS			
Shutters	GOOD ✓	NONE	
Protection bars... ..	NONE ✓	--	
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	GOOD ✓	NONE	
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	NONE ✓	--	
24. LOAD LINE MARKS			
	WELL CUT AND CLEARLY MARKED ✓		



© 2021
Lloyd's Register
Foundations



© 2021

Lloyd's Register Foundation

012108-012112-0138 1/2

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
ALL /	<i>E.J. Thomson</i>	ABADAN	10TH MAY, 1945.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *E.J. Thomson* place ABADAN Date 10TH MAY, 1945.

Signature *E.J. Thomson*


Date 10TH MAY, 1945.

† Insert "all" in case of a complete survey.

10 MAY 1945
A.P.S.

Fee £.2.10.0
Taxi hire £.4.0.0
Number of Visits one

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register
Foundation