

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

1. MAR. 1965

Ship's Name ~~SS/MS~~ FRISTON DOWN

Gross tons 80

LR 640893

Is there a rpt. 9? YES

Port LONDON

Rpt. No. 153548

No. of visits 1

First date AND

Last date 19/2/65

Interim Cert. issued & copy herewith? YES

Damage rpt. issued & copy herewith? NO

Last rpt. (H.Q. only) HUL 70160

Date of completing rpt. 19/2/65

Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. AFLOAT

Last date of examination in D.D.

Has a Load Line Survey been held? NO

Freeboard Marks verified NOT ASSIGNED

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

NIL

25 FEB 1965

NIL

S.A. fee

I have surveyed the above ship in accordance with the Rules for ASCERTAINING THE CONDITION ON ARRIVAL IN THE SERVICE AREA.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

VESSEL EXAMINED AS FAR AS PRACTICABLE WHILE LYING AFLOAT

I recommend that this ship remain as classed with/without fresh record of dry docking SUBJECT TO ANY OUTSTANDING CONDITIONS OR CLASS BEING DEALT WITH AS PREVIOUSLY RECOMMENDED.

Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee

FRIDAY 12 MAR 1965

Minute

+AI Tug. River Thames Service.

+LMC ES TS(OG) } 10.64

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Webs

Lloyd's Register Foundation

hul - HOLL
mch - GLS.

MAR 1965

pt. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~SS/MS~~

FRISTON DOWN

S.S. () Due

Port LONDON

Rpt. No. 153548

Examined & conditionExamined & condition

in dry dock from	-	* Air & sounding pipes	Good
" " to	-	Doublers under " "	-
Shell plating	-	Steering arrangements (main)	Good
Sternframe	-	" " (aux)	Good
Rudder	-	Windlass	-
Has rudder lifted?	-	Masts & rigging	-
Plating, etc. in way of shell openings	-	Hand pumps & suction	-
Side scuttles & deadlights	Good	W.T. doors	-
Overbd. scuppers & discharges	-	Bulwarks, freeing ports, etc.	Good
F.P. spaces	Good	Summer freeboard as verified	-
Chain locker	-		
A.P. spaces	Good		
Engine space	Good		
Boiler space	-		
Under E. & B.	-		
Coal bunker	-		
Tunnel & well	-		
Cement, asphalt, etc., on btm. shell	-		
Weather decks	Good		
* Casings	Good		
* Deckhouses	Good		
* Superstructures	-		
* Skylights	Good		
* Companionways	Good		
* Hatchways	-		
* Ventilators	Good		


EQUIPMENT:

	Equipment letter	
	Fee ltr., if diff. from eqpt. ltr.	
	Anchors: No. on board	1 B
	State if ranged	
	Length on board	STATED COMPLETE
	Mean dias. range from	to
	Rule length	Dia.
	Mooring ropes	SUFFICIENT

Other items:

These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Surveyor to Lloyd's Register of Shipping

Foundation

012108-012112-0183 2/2