

Dept

Fran

3m.2.56.

1

Now "TERUTAMA MARU"

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl Se. Sr RAIPUT

Report Gok

No. 18404

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry

When due \_\_\_\_\_

✱ 100 A. I. (Steel)

2 dks (stl - UD ft. tanks)

Cell DB 350' height DTA 33' 900t FPT 118t. APT 31t

FK, 8BH (1 to 2<sup>nd</sup> dk), ft. Conn, Lloyds A & CP

P 40' B 140' F#7'



© 2021

*W. H. H. H.*

4. 6. 15.

012273-012278-0052

Lloyd's Register  
Foundation

Brack