

# CONDITION OF CLASS.

NAME OF VESSEL... "BARBOSA".....

Extract from freeboard verification of marking form received  
from the ..... GREENOCK ..... Surveyors dated the. 21.6.39. /

Moulded depth	9	ft.	0	ins.	/
Corresponding draught	6	ft.	10 $\frac{1}{4}$	ins.	/
Moulded depth as shewn on draught sheet	9	ft.	0	ins.	/
Tropical Freeboard	2	ft.	1 $\frac{1}{2}$	ins.	/
Summer	"	2	ft.	3 $\frac{1}{4}$	ins.
Winter	"	-	ft.	-	ins.
W.N.A.	"	-	ft.	-	ins.
Fresh Water allowance			1 $\frac{3}{4}$	ins.	/

Marked from ~~xxxx~~/steel upper deck. /

Checked by..... *DM* .....

Date. 18.7.39.....



© 2021

Lloyd's Register  
Foundation

012 353-012400-0274