

Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Non-Propelled Barge "TEXACO 396" Report N.Yk. No. 37370

For the CHIEF SHIP SURVEYOR ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey Classification and Damage When due --

A- Barge to be Towed.

For Service between Eastport, Me. & Norfolk, Va.

Carrying Petroleum in bulk.

1 Dk. Longitudinal Framing.

FK, 6 BH.

Electrically welded.

1,37 N.Yk.

S.S.N.Yk.No.3-1,37.

Handwritten: f see Appendix to Texaco 396
 Supplement - attached to Report 37370



© 2021

Lloyd's Register
 Foundation

The Surveyors should be requested to forward the overall length in accordance with Circular No.1703