

2 E

E 1 MAY 1948

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

"LAURENTINO" ex. "JAN DE WAELE" REPORT Lis. No. 4533

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

PLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. NO.

is Survey, due 8.47 ^{now} held ~~partly~~ ~~not~~

and the following repairs carried out (due to wear & tear):-

A number of defective stays renewed and
screw shaft examined.

is submitted the vessel is eligible to remain as classed, with

of

BS 3.48,

S 3.48,

as recommended.

Yhr

30. 4. 48.

012431-012438-0235