

Messrs, Gebr. Niestern & Co. Delfzijl.

Yard No. 243.

SISTER TO "SAMUDERA"

of Ship Surveyor

Received from Chief Ship Surveyor

NAME m.s. "BLEKOK"

REPORT

Gro.

No. 727

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Framing .. As approved.

Sheerstrake .. As approved.

L. 114.83' B. 21.33' D. 9.66' Proportions 11.86 to Upper Dk.
6.93 to Bridge Dk.

The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

It is therefore submitted the ship is eligible to be classed :-

LOCAL "For Service in the Indonesian Archipelago"

8,52 Dzl.

WHEN a satisfactory report as to the ship's condition on arrival in the Indonesian Archipelago has been received.

1 Dk, "pt Elec. welded"

3qt

Cell DBa 25' uE 21' f 30' pt W.B. (55t) pt O.F. pt F.W, Side tanks in mchy space O.F.

FK, 6BH, Lloyd's A & CP

B & F 48'

"C"
13/16

Port 11/2 7/8 11/9 5/10

REVISED CERTIFICATE

It is further submitted the Surveyor at DJAKARTA be requested to carry out a General Examination of the ship on her arrival in the Indonesian Archipelago and submit a Report 8 on the case.

R.S.P

7.10.52.



© 2021

Lloyd's Register Foundation

012460-012472-0267