

Eng  
Gross  
Less C  
Less a  
Eng  
TONNA

Im.12.15.

F.E.

Received by Chief Ship Surveyor 22-6-16

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel Lug Pinky Rpt. Shel No. 29372

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 29.5 Depth "d" 9.33

Framing: Table No. 3 page 9 Description Single angle as approved

Longitudinal No. 2507

Proportions Length = 8.1  
Depth = \_\_\_\_\_

~~Deck~~ Sheerstrake a. per Rule.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\star$  100 A.1. (Steel) for towing purposes, as recommended.

$\star$  100 A.1. (Steel) for towing purposes

1.0%

a.p.t. 56

BK 6. 4BH. a. Laser.

*M*  
22-6-16



© 2021

Lloyd's Register  
Foundation

012514-012526-0218

BEA