

LLOYD'S REGISTER OF SHIPPING

Hd 12/23
16 JAN 1956


REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship....."ESSO SUWANEE"..... Official Number.....168217..... Port of Registry.....London.....
Place of Survey.....Ellesmere Port..... Dates of Survey.....2. 1. 58..... Date of last Load Line Survey.....3rd Oct. 1956.
issue
Cert valid 2/10/61
SS. (DA) 10/56

PARTICULARS OF SURVEY

Items examined.	Condition in which found.	Repairs.		
		Necessary.	Date effected.	
HATCHWAYS, INCLUDING SMALL HATCHWAYS.				
1. Exposed on freeboard decks.				
Coaming, their stays and stiffeners ...	Good. ✓			
Beams ...	-			
Fore and afters ...	-			
*Covers ... Steel hinged Q.T. ...	Good. ✓			
*Tarpaulins ...	-			
(State number per hatchway)				
* Cleats and battens Bolts Toggles & Jointing	Good. ✓			
Lashings and their fittings ...	-			
Wedges ...	-			
(Is supply, including spares, adequate?)				
2. Exposed on superstructure decks, including raised quarter decks.				
Coamings, their stays and stiffeners ...	Good. ✓			
Beams ...	-			
Fore and afters ...	-			
*Covers ... STEEL W.T. ...	Good. ✓			
*Tarpaulins ...	-			
(State number per hatchway)				
* Cleats and battens Toggles and jointing	Good. ✓			
Lashings and their fittings ...	-			
Wedges ...	-			
(Is supply, including spares, adequate?)				
3. Within superstructures not intact or not protected by Class I closing appliances.				
Coamings ...	-			
Beams ...	-			
Fore and afters ...	-			
Covers ... STEEL W.T. ...	Good. ✓			
Tarpaulins ...	-			
(State number per hatchway)				
Cleats and battens Bolts & jointing	Good. ✓			
Wedges ...	-			
(Is supply, including spares, adequate?)				
VENTILATORS IN EXPOSED POSITIONS.				
4. To spaces below freeboard deck.				
Coamings, their supports and deck connections ...	Good. ✓			
Closing arrangements ...	Good. ✓			
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.				
Coamings, their supports and deck connections ...	Good. ✓			
Closing arrangements ...	Good. ✓			
AIR PIPES.				
6. Exposed on freeboard and superstructure decks.				
Closing arrangements ...	Good. ✓			
7. Within superstructures not intact or not protected by Class I closing appliances.				
Closing arrangements ...	-			
MACHINERY CASINGS.				
8. Casing Top.				
Fiddle openings, their covers and fastenings ...	-			
Skylights, their fastenings, covers and lashings ...	Good. ✓			
9. Exposed on freeboard and raised quarter decks.				
Doors and fastenings ...	-			
10. Exposed on superstructure decks other than raised quarter decks.				
Doors and fastenings ...	Good. ✓			
11. Within superstructures not intact or not protected by Class I closing appliances.				
Doors and fastenings ...	-			
12. FLUSH BUNKER SCUTTLES and chain attachments				Good. ✓
13. COMPANIONWAYS, including deckhouses enclosing ladderways.				
Doors, fastenings covers, ...	Good. ✓			

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (i)).



© 2021

Lloyd's Register
Foundation

012542-012548-0052

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	Good. ✓		
Bridge, fore end	-		
Bridge, after end	-		
Poop In tact...	- ✓		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	-		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good. ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
	Good. ✓		
18. GUARD RAILS			
	Good. ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	-		
20. LIFELINES (fittings and materiel)			
	Good. ✓		
21. FREEING PORTS.			
Shutters	-		
Protection bars	-		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	Good. ✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
	Good. ✓		
24. LOAD LINE MARKS			
	Verified. ✓		

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
All	Thos J Roberts	Ellesmere Port	2nd January 1958.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the position of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor Thos J Roberts Place Ellesmere Port Date 2nd Jan, 1958.

Initial
24/1/58

Signature Thos J Roberts
Date 2nd Jan. 1958.

Fee £3/- + expenses 17/4.

Number of Visits One.

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.