

Less Engine Room 87.03
Less Navigation Space 17.16

" " Long Bridge Deck } 9.33
" " Room at side to top of hull } Port belonging to

2m.3.

~~WILSON~~

N.N. GLAS. ISLAND

1

Sent to Chief Surveyors

21/7/10

Received from Chief Surveyors

VESSL'S NAME

St J & Kinnaird Head

Report

Uo

No.

29/06

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ 100A1 (2nd)

1st (2nd)

Will due

WB. F.P.T 160

3BH. Gun. Lloyd's 2160 Q38 B 10 F 18 "Mehy Aft"

Calculated
21/7/10



© 2021

Lloyd's Register
Foundation

012553-012563-0198

" " in hold

" " way of latching

" " Deck. Material and thickness

pp