

Rpt. 9

Date of writing report 25th May, 1962

Survey held at Havana, Cuba

REC'D NEW YORK JUN 4 - 1962

Received London

No. of visits 1

Port Havana, Cuba

No. 2008

First date 18th May, 1962 Last date 18th May, 1962

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 15318 Name M.V. "INDIAN REEFER"

Gross tons 2600 Date of build 11/1939

Owners J. Lauritzen

Managers

Port of Registry Esbjerg

Engines made Hsg. By Helsingors Jernsk & Msk.

Type

No. of Main Engines 2 No. of Screws 2

Records of Survey & Special Notations as per Register Book

No. of Main Boilers W.P.

No. of Aux./Donkey Boilers W.P.

Surveyed Afloat or in Dry Dock Afloat

Nature of Survey Machinery (C.S.)

Was Damage Report issued? Int. Cert.?

Last Report (For Head Office only)

Hull			Machinery		
100A1	-	9/61	LMC	(C.S.)	9/61
S.S.	-	9/61	C.L.	p & s	7/60
With freeboard			Lloyd's RMC (R.S.)		
Str. nav. Ice					

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Wear Down of Stern Bushes Oil Glands Sea Connections

Fastenings Has Screwshaft/Tubeshaft been drawn? Date of Examination Has Shaft been changed?

Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides Side Centre

4 Crankpins & Bearings Side Centre

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS The Machinery of this vessel so far as now seen is in fit condition and eligible in my opinion to retain as classed with record of Machinery (C.S.) with date when the Survey has been completed.

Date of Committee

Decision

NEW YORK

JUN 13 1962

Noted for Header

© 2021 Lloyd's Register Foundation

012705-012710-0261

32 Essential Independent Pumps (Identify by position) Bilges pump, at starboard side, forward, good

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers

36 Lub. Oil Coolers

37 Heaters (state service)

38 Independent Air Compressors, Coolers & Safety Devices

39 Air Receivers & Safety devices—Main

40 Auxiliary

41 Oil Fuel Tanks (Not forming part of hull structure)

42 Evaporators

43 Have Evaporator Safety Valves been tested under steam?

44 Steering Machinery

45 Windlass

46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD		AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			
c Air Coolers			m Motors
d Motors			
e Air Coolers			n Switchboards & Fittings
f Control Gear, Cables, etc.			o Circuit Breakers
g Insulation Resistance			p Cables
h Insulating Oil Test			q Insulation Resistance
i Overspeed Governors			r Steering Gear Generators and Motors
j Magnetic Couplings			s Navigation Light Indicators
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN

AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat.
Spt.

Boiler Securing Arrangements

Main Economisers

Exhaust Gas Heated Economisers

Steam Heated Steam Generators

Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules?

Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?

Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main

Auxiliary (over 3 in. bore)

Were Copper Pipes annealed?

Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

LEAVE THIS SPACE BLANK

Survey fees \$ 40.00

Damage fee

Expenses

\$ 1.20

Date when rendered

© 2021

Lloyd's Register
Foundation