

Survey fees

COPY

Ship's name "LUCERNA"

Port

Fal

No. 14307

Last survey date 3.11.62.

Class is subject to

For conditions of class see previous endorsement.

S.R.L. Appendix (as before ~~or none~~)x

Nature of present survey (afloat and in drydock)

Docking: Wear and tear repairs:

Damage repairs (various causes) including part subject items.

Recommendation

SUBMITTED record of 'DS 10,62' be assigned, subject to set up bottom plate A.4 (p.s. from aft), A.4 (p.s. from fwd) being examined and dealt with as necessary next drydocking but without other conditions.

DS 10,62 Subject  
Without.

IN S.R.L. APPENDIX.

Shell plate H.7 (s.s.a) indented.

End. S.1

Ship Plans

Ship Research 6 28/11/62

C.S.S. Record

TO NOTE

012827-012835-0249

S.R.L. Appendix. Indented shell plate H.7 (ssa).

ALSO FOR