

Messrs. A.G.Weser, Breme

9,80 M

Yard No.1343.

10,60 Bk.

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB

SHIP NAME Crane Pontoon m.s. "GABBAR"

REPORT

Bmn.

No. 4892

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/62.)

L. 161'-9"

B. 64'-11 1/2"

D. 13'-9 1/2"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letters.

In a letter dated 12.4.61 the Alexandria Surveyors state that the pontoon was generally examined and found in good condition.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*100A1 "For Service between Suez & Alexandria"

Descriptive Notation "Crane Pontoon"

1 dk; EW.

O.L. 162'-5"


E.B: 65'-8"

Btm tanks in mchy space pt O.F. pt F.W.

2BH; LACP.

R.O.F: 8"

(o) 1.3/8" SQ



IT IS FURTHER SUBMITTED the Alexandria Surveyors be advised that in future similar cases the general examination must be reported on a Rpt.8.

IT IS ALSO SUBMITTED the Bremen Surveyors be requested to furnish particulars of approval of the stockless "Union" type "Pent" anchors supplied as these do not appear to be on the approved list of anchors in this Office.

Issued Certificate
7.6.61

Sent Alex.
E7 JUN 1961

See letter dated
20/6/61

DA.

18.4.61.



© 2021

Lloyd's Register
Foundation

012868 - 012874 - 0075

+ 100 A) For Service between