

SISTER SHIP: 2"YESILIRMAK 3".

Received by Chief Ship Surveyor  
Non-prop Crane Pontoon

Received from Chief Ship Surveyor

SHIP'S NAME "YESILIRMAK 2" REPORT ROT. No. 52843  
EA

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 111'-7"

B. 42'-8"

D. 8'-10½"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letters.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

100A1 "Black Sea & Eastern Mediterranean Service".  
DS 11,61.

Descriptive Notation - Pontoon for sheerlegs.

WHEN a report has been received of its satisfactory condition upon arrival within the service limits.

1 dk; LF; EW.

O.L. 112'-0"

E.B. 43'-0"

Centre tanks amids OF; APTs pt WB 64t pt FW.

4 BH; LACP.

R.O.F. Nil



(f) 1.1/8" f 1½"a.

IT IS FURTHER SUBMITTED in connection with their Report C11 that the Surveyors be informed it is concluded that the scantlings of machinery casings and superstructures are in accordance with approved plans.

The ISTANBUL Surveyors should be requested to generally examine the ship on its arrival within the service limits and forward a Report 8.

C.S.S. Records Dept.  
to note.

Ship Register  
Card prepared.



© 2021  
9.2.62.

Lloyd's Register  
Foundation

012876-012887-0247