

1m,11,30.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Non-Propelled Barge "TEXACO 398" Report N.Yk. No. 37372

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Classification and Damage

When due

A- Barge to be Towed.  
For Service between Eastport, Me. & Norfolk, Va.

Carrying Petroleum in bulk.

1 Lk. Longitudinal Framing.


PK, 6 BH.

Electrically welded.

1,37 N.Yk.

S.S.N.Yk.No.3-1,37.

The Surveyors should be requested to forward the overall length in accordance with Circular No.1703



© 2021  
Lloyd's Register  
Foundation

012925-012932-0025