

to Chief Surveyors _____

Received from Chief Surveyors _____


VESSEL'S NAME Stl T.S.M.V. "KOOLINDA" Report Gls No. 46230

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 21/5/92.)

Signature of Surveyor 1st Entry When due Revised Rules

✠ 100 A.I. (Steel). "With Freeboard"
 2 Dk (Stl- Weather Dk leaks), 3rd Dk (Stl) in Forward Hold
 Cell D.B. 230' 5275, D.T. 24' 5715, F.P.T. 1705, A.P.T. 1205.
 F.K, 7 BH (5 BH to weather Dk, 2 B.H. to 2nd Dk), pt Cem, Lloyds Ar CP.
 B 220', F 44'.



© 2021 Lloyd's Register Foundation

[Handwritten signature]
 207.27
 13.1.27

The Surveyors should be requested to forward the casting report for the stemframes
 013409-013416-0284