

For the information of Surveyors and the Committee only.

Received at

Office

19

# Lloyd's Register of Shipping.

(Report on Vessel No. 1422 Port bdz)

## No. 154 SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Soc. Esp. de Constr. Naval of Reinosa for the Vessel No. 27, being built by Echevarrieta y Laminaga of Badaj have been inspected by me as set forth below and found to be, so far as can be seen, sound & free from defects.

on ~~Forgings or~~ Castings.

Lloyd's

No. 104

19-7-32 ad.

G. Dixon.

Bilbao.

### DOUBLE SHAFT BRACKET.

	<del>STERN FRAME.</del>	RUDDER FRAME.	STEM.
Material* ...	<u>Spec. Yarn. Steel</u>		
made ...	<u>best</u>		
annealed ...	<u>yes</u>		
Dimensions ...	<u>10590 kgs.</u>		
Press on Inspection ...	<u>Cast &amp; rough mach'd</u>		
when Inspected	<u>18-7-32 &amp; 19-7-32</u>		
CASTINGS.			
Tests on Standard Test Pieces.			
Weld Test—			
Welds per square inch ...	<u>47.8</u> <u>47.8</u>		
Extension per cent. ...	<u>38</u> <u>21</u>		
Bending Test—			
Angle before fracture ...	<u>120° bent</u> <u>120° bent</u>		
Weld Test—			
Height from ground ...	<u>Iron tests taken</u>		
Tempering Test—			
If made according to Rules and found satisfactory ...	<u>Yes.</u>		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ : :

To be paid at

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

013671-013677-0097