

The Grangemouth Dockyard Co. Ltd., Grangemouth. Yard No. 526.

to Chief Surveyors

GB

S NAME

M.S. "MOANA ROA"

Received from Chief Surveyors

CLASS CONFIRMED 29/9/60

REPORT

Gls.

No. 91590

For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

of Survey FIRST ENTRY

XXXXXX

L. 270'-0"

B. 46'-0"

D. 22'-0"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letter

*100A1
DS 6,60.

1 dk; 2nd dk fwd. of mchy space; pt EW.

O.L. 296'-6"

E.B. 46'-3"

ESD; RDR; PFD; DF; GC.

DB pt W.B. 272t pt O.F. pt F.W; Tunnel side tanks F.W; MTf O.F;
FPT 6lt; APT 56t.

7BH: LACP

P & B 154' F 36'

R.O.F: 6"

"t" 1.5/8" SQ

INSERT IN S.R.L. APPENDIX.

(Ferobestos rudder bearing bushes to be examined in dry dock after about 12 months and behaviour in service reported upon).



DA

15.9.60.



© 2021

Lloyd's Register
Foundation

013884-013889-0035