

Condition of ~~Ship~~

Tonnage Opening Fitted.

NAME OF VESSEL....."PORT JACKSON".....

Extract from Freeboard Verification of marking form received
from.....Newcastle.....Surveyors dated.....6.1.37..

Moulded depth	33	ft. 5	ins.
Corresponding draught	28	ft. 5 $\frac{1}{2}$	ins.
Moulded depth as shewn on draught sheet	33	ft. 5	ins.
Tropical freeboard	4	ft. 6 $\frac{3}{4}$	ins.
Summer "	5	ft. 1 $\frac{3}{4}$	ins.
Winter "	5	ft. 8 $\frac{3}{4}$	ins.
Winter North Atlantic freeboard	+	ft. -	ins.
Fresh water allowance	7	ins.	

Marked from ~~wood~~/steel upper deck.

Checked by.....*km*.....

Date..8.2.37.....



© 2021

Lloyd's Register
Foundation

013961-013971-0076