

2m. 12.35.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME St S PASS OF MELFORT Report Sl No. 45890

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due _____

✱ 100 A.I. (Steel). Carrying petroleum in bulk

1 D¹⁶ (Stl) • web frames, longitudinal framing.

Cell D.B. E 22' 19t, D.T.f 11' 39t, F.P.T. 22t, A.P.T. 27t.

F.K, 9B.H, pt asp, Lloyd's A.C.P.

P 74', TRUNK 84', F 23'. "machy apt."

} subject to the
Cables • windlass
being placed in
order.

The London Surveyor should be advised

013972-013979-0295



© 2021

Lloyd's Register
Foundation

19.8.26.
4589