

F.E.

ed by Chief Ship Surveyor 5-4-18

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheelss Mangan Jones

Rpt.

Lm

No. 80702

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Transverse No.

36-87

Depth "d"

12.16

Framing: Table No.

3 page

Description

Single angle as approved

Longitudinal No.

4608

Proportions

Length

Depth =


9.26

~~Deck~~ Sheerstrake

- 5 of an inch instead of 3-36 as reqd

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\frac{1}{2}$ 100 A-1. (Steel) Steam Trawler, as recommended.

1.5K

BK $7\frac{1}{2}$ 3BH Cam. Lugs over. Q73 F21

6.4.18


© 2021

Lloyd's Register
Foundation

014185 - 014197 - 0131