

COPY

Ship's name MONTE AYALA

Port BILBAO

No. 13724

Class is subject to

Last survey date 25.6.64

1. The port inboard aft auxiliary diesel generator engine (temporarily repaired 7.63) to be used only in an emergency and to be permanently repaired or renewed by 4.64 (9 months limit).

Docking & TS WD 4mm.

SRU item above crankshaft
replaced & engine tested. Item
to be deleted

CSM advanced


Surveyor states additional electrically
driven air compressor from GL
classed vessel 'Falkenfels' satisfactorily
installed on board. The air discharge
piping has not been tested. The

Surveyor recommends air discharge
piping from starboard air compressor
to air receiver being made to
comply with Rule requirements at
end of present voyage

TS, CL 6/64 subject as now
recommended only

014556 - 014565 - 0218

13/8/64



© 2021

Lloyd's Register
Foundation