

Deck Factor "F" excluding d.

Owners

British Transport Commi

Messrs. Richard Dunston(Hessle) Ltd.,Hessle.

Yard No.S.782.

9.61 Blk.

ived by Chief Ship Surveyor

GB

Non.Prop.Grain

Received from Chief Ship Surveyor

IPS NAME

Elevator Pontoon "CARNABY"

REPORT

Hul.

No. 68126

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 87'-6"

B. 39'-0"

D. 14'-0"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretaru's letters.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*Al "Hull Docks Service"
DS 7,62.

Descriptive Notation:- "Grain Elevator Pontoon"

1 dk; EW.

O.L: 87'-10"

E.B: 39'-4"

Side & cr. tanks f pt WB 39t pt FW, a pt WB 39t pt FW.

2BH; LACP

R.O.F: Nil

(f) 15/16"



C.S.S. Records Dept.
to note.

Ship Register
Card prepared.

DA.

9.11.62.



© 2021

Lloyd's Register
Foundation

014556 - 014565 - 0407