

his services for this purpose and to whom and why they were declined.

... painted on Ship a

Was a damage report made by anyone else? if so, by whom

MEMORANDUM



9 NOV 1949
(Ref. H.)

S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

or(s) at **HONG KONG.**

Date: **16th September, 1949.**

S.S. "HAI YUN".

QUESTION.

ANSWER.

Date:— **31st October, 1949.**

shall be glad if you
ertain from the Owners
me know what arrangements
pose making to carry
Screwshaft Survey
came due at the end
last.

This vessel was in a Yangtze
River Port at the fall of Shanghai
and at present the location of the
ship is unknown to the Owners.

J. Muller

L.P.



© 2021

Lloyd's Register
Foundation

014604-014618-0056

Plating.....	examined and found efficient	Stringers, Clamps & Shelves.....
ts been examined internally?.....	Air and Sounding Pipes.....	Salting
ks been tested?.....	Doubling Plates, under Sounding Pipes.....	State if examined