

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

GB

SHIP'S NAME m.s. "MONTROSE"

REPORT s Sld. No. A.38
Sld. No. A.39

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

L. 421'-6"

B. 58'-6"

D. 35'-9"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letters.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

*100AL "MTf - vegetable oil"
DS 3,61.

OSD, 1 dk & S dk, 3rd dk in way of Nos. 1,2 & 3 holds;
LF at btm & dks; pt EW.

O.L. 440'-0"

E.B: 58'-8"

ESD; RDR; DF; GC

DB pt W.B. 1058t pt O.F. pt F.W; Wing & centre tanks in mchy space O.F;
MTf 992t; Tween dk tanks aft F.W; FPT 44t; APT 111t.

Coll BH to S dk, 6 to 2nd dk; LACP.

F 39'

R.O.F: 3"

"b†" 2.1/16" SQ

C.S.S. Records Dept.
to note.

P.5 Steel.

INSERT IN S.R.L. APPENDIX.

(Main structure partly of P.5 Steel).

SHIP completed in OSD condition.



R.S.S.

9.6.61.



© 2021

Lloyd's Register
Foundation