

Amidships, Angle, ~~E or F~~

5 3 34

" " top Angles

Surveyors

Received from Chief Surveyors

NAME Stl S " LADY COMBE " Report Gls No. 47324

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Entry

1st Entry

When due

Revised Rules.

✱ 100 A. I. (Steel). Dredger } subject to steel deck being sheathed
 1 D^K (Stl). } with 2 $\frac{3}{4}$ " Cement on vessels
 M.T. 15 t. } arrival at Lagos.
 F.K, 5 B.H, Cem, Lloyds ACP



© 2021

Lloyd's Register Foundation

014738-014750-0174

Angles

Angle

0 32 30

Poop Deck, Angle, ~~E or F~~