

F.E.

1m.10.33.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Tw.Sc. Suction Hopper Dredger
"CHIEN SHE"

Rpt.

Gdy

No.

1370

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

1st Long. No. 9540

Depth "d" -

2nd Long. No. 31140

Proportions = $\frac{L}{D}$ -

Framing bulb angle frames as approved

Sheerstrake as approved

This vessel appears to have been built in accordance with the
plans and the approved plans, and it is submitted she is eligible to
be classed

✱ 100A1 Hopper Dredger

1 Dk

Hopper Side Tanks 107' 254t FPT 160t APT 157t

FK, 6 EH, pt. cem. pt. asp., Lloyd's A & CP

Machy. aft

Rudder electrically welded

The Surveyor should be requested to forward the usual forging reports
the also endorsement 4/13/35 re fus

Advisi Shanghai Surveyor

Ltr. Shi. 16/3



© 2021

Lloyd's Register
Foundation

5.3.35