

7m.10.47.

Received by Chief Ship Surveyor

GB

VESSEL'S NAME

"G Y D A"

Received from Chief Ship Surveyor

B.C.  
26 OCT 1949

REPORT

Ham.

No.

654G

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

This vessel is classed BS\*

A Type 3 SPECIAL SURVEY and an Annual Survey for Classification became due 12.50 and 12.49 respectively.

The HAMBURG Surveyors' report (5.49), the vessel placed on floating dock, bottom coated, and in consequence of damage through striking quay walls, repairs effected to indented shell plating, etc.

On account of heavy weather and collision damages, repairs effected to forecastle side and bulwark plating, etc.

Repairs also effected to windlass and steering gear.

Nos. 1 & 7 D.B. tanks previously used for water ballast have been fitted for oil fuel.

IT IS SUBMITTED the vessel is eligible to remain as classed by the British Corporation, with record of docking survey 5.49.

BS\*

5.49 Ham.



© 2021

Lloyd's Register  
Foundation

014771-014776-0315