

Port of

Newcastle

29 APR 1941

April 28/41

REPORT ON MASTS, SPARS, AND RIGGING. ✓

Dear Sirs

Having, in accordance with your instructions,
examined the Masts, Spars, Iron Work of same, and Rigging, of the

Name of Vessel) *SS Elna II, lying at the Middle Rocks.*

on the (Date of examination) *April 28/41* 19*41*,

I have to report that I found *Main Riggings Port and Starboard, Main Topmast, Backstays Port and Starboard, and Main Stay. Stranded, Pitted and Strained. Recommend the renewal of the above screws and shackles of the renewed Wires to fore, and repair where necessary. Main Mast, Pitted and Holed at Derrick Double Eye Plates on after side. Recommend the Mast to be cleaned for examination and repairs. Main Mast Wedges are not drawn. Fore Mast, Spars, other Rigging and Ironwork in good condition.*

H. Pearson

Fee £

To the Surveyors,

Lloyd's Register of Shipping,

Newcastle on Tyne