

request form signed by the Owner.

.....156
.....11

D REPORT on the ST THERESE

It is submitted the Sunderland Surveyors be requested to obtain the following information from the Builders, Messrs. Swan Hunter Wigham Richardson yard no 1327

1. The moulded displacement at a moulded draught equal to 85 per cent. of the moulded depth;
2. The external displacements and tons per inch at actual draughts:- 18' 6"

mentioned Lulla 10/12/32



© 2021

Lloyd's Register
Foundation

015366 - 016319 - 0452

4
0
4
2
7
6
1
2
5
2
0
7